

Ortiz Ditch

The list of individual owners, showing the findings of the hydrographic survey, is as follows:

Armando, Kelly

(1) Map Sheet 2, Tract 45

A. Use - Irrigation:

a. State Engineer File No.: 0105

b. Source of water: Surface and groundwaters of the Pojoaque River System

c. Irrigated lands:

Part of P.C. 70, Exception 188, P.5 Sec. 8, T. 19 N., R. 8 E., within the San Ildefonso Pueblo Grant, as shown on hydrographic survey map sheet No. 2, Tract 45.

None

In the above description, 0.35 acres were found to be fallow more than four consecutive years by field check on September 11, 1963.

(2) Map Sheet 2, Tract 46

A. Use - Irrigation:

a. State Engineer File No.: 0105

b. Source of water: Surface and groundwaters of the Pojoaque River System

c. Irrigated lands:

Part of P.C. 70, Exception 188, P.5 Sec. 8, T. 19 N., R. 8 E., within the San Ildefonso Pueblo Grant, as shown on hydrographic survey map sheet No. 2, Tract 46.

3.30 a.

Duran, Antonio C.

Map Sheet 2, Tract 48

A. Use - Irrigation:

a. State Engineer File No.: 0105; no file was found for the well described below.