


Figure 26. Map showing approximate saturated thickness of the Ogallala Formation, 1952, Lea County, New Mexico.






Figure 28. Map showing approximate saturated thickness of the Ogallala Formation, 1995–1998, Lea County, New Mexico.

JOHN SHOMAKER & ASSOCIATES, INC.




Figure 29. Map showing changes in specific conductance, 1948–1958, Lea County, New Mexico.