

EXAMPLE: Bank-line Modification in the Rio Grande



Before construction - March 2009 Bankline mostly Russian olive and Saltcedar



After construction - April 2009



Amphibious excavators working in the river channel



Today - September 2009 Native species are now present including coyote willow and cottonwood